**J T BEVANN DRYLINING SPECIALISTS LTD**

| **WORKPLACE RISK ASSESSMENT NUMBER: 012** | **DATE**: 30.09.04. |
|---|---|
| **LOCATION:** | |
| **OPERATION/PROCESS**<br>PLASTERBOARDING | **MANUAL HANDLING ASSESSMENT**<br>Will be required for each Operative as required. |
| **EQUIPMENT USED**<br>Hand Tools & Power Tools | **COSHH ASSESSMENT**<br>As per manufacturer's data sheets |
| **SUBSTANCES USED**<br>Plasterboards/Compounds/Metal Sections/Screws | **NOISE ASSESSMENT** |

| **Hazards Identified** | Before Controls | | | | After Controls | | |
|---|---|---|---|---|---|---|---|
| | **L** | **M** | **H** | | **L** | **M** | **H** |
| Manual handling | | X | | | X | | |
| Back strain | | X | | | X | | |
| Cuts and grazes | | X | | | X | | |
| Dust | | X | | | X | | |

**Exposed Persons:** Operatives and bystanders/colleagues

| **FREQUENCY OF EXPOSURE** | **DURATION OF EXPOSURE** |
|---|---|
| Varied | Varied |

**CONTROL MEASURES P.P.E. INSTRUCTION/INFORMATION/TRAINING**

COSHH assessments made available to Operatives along with Manufacturer's data sheets.
Training and information is provided on how control measures should be applied.
Appropriate personal protective equipment is provided and worn.
Good ventilation in areas of work.
Dust masks to be worn when mixing materials.
Clean water to be used for mixing of materials.
Hop-ups and access equipment to be checked daily to ensure they are in good condition.
All labour will undertake Manual Handling and team work training and will be made aware of the weights and sizes of all relevant materials.

**MONITORING RESULTS**

| **ASSESSOR** | **POSITION** |
|---|---|
| | |